


CORNER RECORD

Agency Index Bk. 20 Pg 79Document Number 20180066City of Rocklin County of Placer, CaliforniaBrief Legal Description Centerline of Cottonwood Court, L Maps 92

CORNER TYPE



- ☐ Government Corner ☐ Control
☐ Meander ☒ Property
☐ Rancho ☐ Other

Date of Survey June 21, 2018

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units ☐ Metric ☐ U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

☐ Complies with Public Resources Code §§8801-8819☐ Complies with Public Resources Code §§8890-8902

SEC 30, T.11N., R.7.E.

PLS Act Ref.: ☐ 8765(d) ☒ 8771 ☐ 8773 ☐ Other:

Corner/
Monument: ☐ Left as found ☐ Established ☐ Rebuilt ☐ Pre-Construction
☐ Found and tagged ☒ Reestablished ☐ Referenced ☒ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☒ See sheet #2 for description(s):

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on July 3, 2018Signed [Signature] P.L.S. or R.C.E. No. 6947

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed July 11, 2018Signed [Signature] P.L.S. or R.C.E. No. 6584Title County Surveyor

County Surveyor's Comment _____




BOOK 20 CORNER RECORDS, PAGE 79

LINE TABLE		
LINE #	DIRECTION	LENGTH
L1	S49°23'12"E	38.43'
L2	S35°09'33"W	38.48'
L3	N13°20'06"W	48.64'
L4	S61°03'22"E	52.24'
L5	N14°54'30"E	18.83'
L6	S01°39'30"E	15.31'

✕ - - - SET CUT CROSS IN SIDEWALK AS REFERENCE POINT
 ✕ - - - FOUND 3/4" IRON PIPE WITH DILAPIDATED PLASTIC CAP (1);
 AFTER RE-PAVING SET RAILROAD SPIKE "LS 6947"
 ● - - - FOUND 3/4" IRON PIPE WITH DILAPIDATED PLASTIC CAP (1)
 (1) - - - RECORD DATA PER L MAPS 92

1217 Pleasant Grove Blvd. Suite 130 • Roseville, CA • 95678
Phone: 916-773-4006 Fax: 916-773-4498



DATE: 7-3-2018